



PLASTIC-PART STRESS INDICATOR

Checks Stress Distribution and Weld-Line Location in Clear and Translucent Plastics


Improves Quality by enabling simple
evaluation of stresses



Light-Intensity Adjustment



Viewing a pair of safety glasses through
the Stress Indicator.



Compact -- Folds into
1-1/2" x 3-1/2" x 5" pouch

Simple to Use

- Hold indicator up to light with molded part between the lenses.
- Stresses show up as darker coloring. Clear places are stress-free.

Part #	PRICE
MPSA	\$95.00

© 2001 MOLDERS CHOICE, Inc.



24 Hour Service - 7 Days a week
1-800-809-4623
 WebSite: www.molderschoice.com • Email: modlers@molderschoice.com